



Account & Contact Information

Account	[REDACTED]	Work Order Number	[REDACTED]
Address	[REDACTED] US		
Phone	[REDACTED]	Subject	[REDACTED] - Tsugami BU38-SY [REDACTED] - Install machine and bar feeder.
Contact	[REDACTED]	Work Type	Lathe - Installation
Contact Email Address		Manufacturer	
Created Date	9/7/2022	Asset	TSUGAMI - BU38SY [REDACTED]
		Serial Number	[REDACTED]
		Machine Control Model Number	

Service Performed

Customer
Complaint

What Did You
Determine Was
Wrong?

What Was
Observed When
Troubleshooting?

Service Performed Installed the BU-38SY they purchased from a company in the Midwest. Leveled and tested and check the functions of the machine out checked for backlash and any other issues. The X1 axis has a little backlash in the ball-screw and bearings. The spindles and live tools sound like the are in good shape. This machine need the work light replaced with the new LED style work light.

Tests Performed?

Parts Info

Safety Checks

E-Stop	Review Safety Failures with Customer	<input type="checkbox"/>
Door Interlocks	Offer to Fix Safety Failures when Onsite	<input type="checkbox"/>
Windows & Guard	Request Quote for failed Safety Items	<input type="checkbox"/>

The Robert E. Morris Company
910 Day Hill Road | Windsor, CT 06095
www.robertemorris.com | 860-687-3300

Morris South
12428 Sam Neely Road | Charlotte, NC 28278
www.morrisouth.com | 704-523-6008

Morris Great Lakes
9151 Marshall Road | Cranberry Township, PA 16066
www.morrisgreatlakes.com | 877-373-8906

Morris Midwest
2323 Corporate Drive | Waukesha, WI 53189
www.morrismidwest.com | 866-797-4410



Pressure Settings

Safety Checks Advisory

Operating machinery is generally safe provided proper safety measures are adhered to. All installed manufacturer safety devices must function properly and work & tooling holding devices must be in proper working condition. The machine must be placed in Lock Out Tag Out condition until all safety items are working properly or the possibility of bodily injury may occur. Only OEM parts installed by a qualified technician should be used. The machine owner is responsible for any issues that may arise due to improper installation, use of unauthorized repair parts or operating the equipment unsafely. If you have any questions on providing a safe work environment, please contact us.

Work Order Line Items

Work Order Line Item Number	Type	Quantity	Start Date	End Date	Service Resource
00000010	Labor Adjustment				Dwight Gunter
00000009	Labor	6.24	9/9/2020 8:52 AM	9/9/2020 3:07 PM	Dwight Gunter
00000008	Travel	1.25	9/9/2020 3:07 PM		Dwight Gunter
00000007	Travel	1.18	9/9/2020 7:41 AM	9/9/2020 8:52 AM	Dwight Gunter
00000006	Labor	7.60	9/8/2020 10:18 AM	9/8/2020 5:54 PM	Dwight Gunter
00000005	Travel	1.25	9/8/2020 5:54 PM		Dwight Gunter
00000004	Travel	2.31	9/8/2020 8:00 AM	9/8/2020 10:18 AM	Dwight Gunter
00000003	Labor	5.66	9/4/2020 9:20 AM	9/4/2020 3:00 PM	Dwight Gunter
00000002	Travel	1.20	9/4/2020 3:00 PM		Dwight Gunter
00000001	Travel	1.20	9/4/2020 8:08 AM	9/4/2020 9:20 AM	Dwight Gunter

The following parts and material were included above as part of this work order's line item detail. They are broken out in this section for quick reference.

Parts & Material

Work Order Line Item	Part Name	Part Number	Quantity Consumed
----------------------	-----------	-------------	-------------------

Tech Signature

Signature

Signed By

Date

Type Tech

Customer Signature

Date

Signature

The Robert E. Morris Company
910 Day Hill Road | Windsor, CT 06095
www.robertemorris.com | 860-687-3300

Morris South
12428 Sam Neely Road | Charlotte, NC 28278
www.morrisouth.com | 704-523-6008

Morris Great Lakes
9151 Marshall Road | Cranberry Township, PA 16066
www.morrisgreatlakes.com | 877-373-8906

Morris Midwest
2323 Corporate Drive | Waukesha, WI 53189
www.morrismidwest.com | 866-797-4410



Signed By

Type

Customer

The Robert E. Morris Company
910 Day Hill Road | Windsor, CT 06095
www.robertemorris.com | 860-687-3300

Morris South
12428 Sam Neely Road | Charlotte, NC 28278
www.morrisouth.com | 704-523-6008

Morris Great Lakes
9151 Marshall Road | Cranberry Township, PA 16066
www.morrisgreatlakes.com | 877-373-8906

Morris Midwest
2323 Corporate Drive | Waukesha, WI 53189
www.morrismidwest.com | 866-797-4410